

SPX Corporation 5885 11th Street Rockford, IL 61109-3699 USA Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031

Internet Address: http://www.powerteam.com


## **Parts List for:**


P59F P59FP
P59F-DICKE P59FV
P59FE P59FR
P59FN P59F-IND

## TWO-SPEED HYDRAULIC FOOT PUMP

325 PSI FIRST STAGE; 10,000 PSI SECOND STAGE







Sheet No. 1 of 2

Rev 10 Date: 24 Oct 2003


Iter No.		No. Req'd	l Description	Item No.	Part No.	No. Req'd	Description
1	•†*215907	2	Decal (Do Not Remove)				(For P59F-DICKE)
2	211743	4	Retaining Ring (Expand the retaining	23	360054	1	Trade Name Decal (For all models
_	10010	0	ring to .440 ø max. during installation.)	0.4	050500		except P59F-IND)
3	10012	3	Soc. Hd. Cap Screw	24	252502	1	Tie Rod
			(1/4-20 X 7/8 Lg.;	25 26	351367 13943	1	Reservoir Assembly
4	251702	2	Torque to 90/100 in. lbs.) Pin	20	†19775	1 1	O-ring (.50 X .37; Urethane) O-ring (.50 X .37; Viton)
5	251702 251716BK9	1	Release Valve Lever Assembly		•17716	1	O-ring (.50 X .37; VIOII)
6	•†*305977	1	Warning Decal (For all models	27	10842	i	Hex Cap Nut (3/8-16; Torque to
·	1 000077	•	except P59F-IND)	_,	10012	•	90/110 in. lbs.; Fully engage acorn nut
	305977-CE	1	Warning Decal (For P59F-IND)				onto tie rod before torquing to body.)
7	10274	1	O-ring (.87 X .68; Nitrile)	28	250328	1	Attention Decal (For P59FE)
	253597	1	O-ring (.87 X .68; Viton)	29	253234	1	Decal (Oil Pivot Pins) On
	253598	1	O-ring (.87 X .68; EPR)	30	250000	1	Recessed Bumper pumps
8	351245	1	Filler Cap	31	12102	1	Soc. Hd. Screw built after Dec. 13.
9	64780OR9	1	Foot Lever (For all models except				(10-24 x 3/4; Apply 1999
	0.4700.03/4.0		P59F-IND)				Loctite #277 or equiv.;
10	64780GY16	1	Foot Lever (For P59F-IND)				Note: End of screw should
10	58048 48011	1	Carry Handle Relief Valve Assembly				be flush with top of pedal.)
11	3000098	1	(for P59F-IND)			INCLU	DED BUT NOT SHIPWN
12	251712	1	Compression Spring		13229	1	Plug Fitting
13	350923	1	Piston Clip				(90°; 1/8 NPTF)
14	•†*250233	1	U-cup		253626	1	Straight Fitting
15	11127	1	Pipe Plug (3/8 NPTF)				(1/8 NPTF; Group towards hall) For P59FP
16	•*†213987	1	O-ring Backup Washer		10423	1	Groove towards ball)  Ball (9/32" Dia. Steel;
			(Assemble with concave surface		10423	'	Seat at assembly)
	******		towards o-ring)		215033	1	Tee Fitting
17	*10271	1	O-ring (11/16 X 1/2 X 3/32; Nitrile)		210000	•	(1/8 NPTF)
	†11445	1	O-ring (11/16 X 1/2 X 3/32; Viton)	;	351934-100	1	Relief Valve (Set at
18	•19406 421412	1 1	O-ring (11/16 X 1/2 X 3/32; EPR) Two-Speed Piston				9,600/10,000 PSI)
19	*12557	1	O-ring (11/32 x 7/32 x 1/16; Nitrile)		350988	1	Decal (CE)
19	†18973	1	O-ring (11/32 x 7/32 x 1/16, Nitrile)		360000	1	Plate For P59F-IND
	•215375	i	O-ring (11/32 x 7/32 x 1/16; EPR)		209541	2	Plain washer }
20	*211495	1	O-ring (2-11/16 x 2-1/2 x 3/32; Nitrile)			_	(.51 x .29)
	†213209	1	O-ring (2-11/16 x 2-1/2 x 3/32; Viton)		251488	2	Screw (1/4-20 x 5/8)
	•215369	1	O-ring (2-11/16 x 2-1/2 x 3/32; EPR)		12809	2	Locknut (1/4-20)
21	•†*215075	1	Plug Filter				То
22	21278	1	High Pressure Relief				Drawing
	04070 55		Valve Assembly				<b>Brawning</b>
	21278-80	1	High Pressure Relief 8,000 PSI				

Part numbers marked with an asterisk (\*) are contained in Standard Repair Kit No. 300814. Part numbers marked with a dagger (†) are contained in Viton Seal Kit No. 300815. Part numbers marked with a bullet (•) are contained in EPR Seal Kit No. 300816.

Note: Shaded areas reflect last revision(s) made to this form.

Parts List Form No. 101783

## **END VIEW**



Item	n Part	No.	
No.	No.	Req'd	Description
1	251753	1	Pin & Chain Assembly
2	•†*14874	2	Copper Washer
3	351952	2	Valve Screw (Torque to 480/500 in. lbs.)
4	215301	1	Decal (Pressure; For all models except P59F-IND)
	252247	1	Decal (Pressure; For P59F-IND)
5	•†*10444	4	Compression Spring
6	•†*10378	2	Steel Ball (3/8 dia.)
7	•†*211797	2	Compression Spring
8	64710	1	Pump Body
	65671	1	Pump Body (For P59FR)
9	•†*10375	2	Steel Ball (1/4 dia.)
10	10479	1	Plug
	10909	1	Plug (For P59FR)
11	11084	1	Plug (Apply Loctite #242 or equivalent & torque to 80 in. lbs.)

Item No.	Part No.	No. Req'd	Description
12	*10658	1	O-ring (1" X 13/16 X 3/32; Nitrile)
	†19002	1	O-ring (1" X 13/16 X 3/32; Viton)
	•215364	1	O-ring (1" X 13/16 X 3/32; EPR)
13	420979	1	Release Valve Body
14	251710	1	Hex Soc. Hd Shoulder Screw (3/8 x 3/8 Lg.; Apply Loctite #242 or equivalent; Torque to 100 in. lbs.)
15	215300	1	Decal (Gauge; For all models except P59F-IND)
	252246	1	Decal (Gauge; For P59F-IND)
	201746	1	Decal (Return; For P59FR)
D - 1			"He are a set a 2-d (#) and a set a 2-d d


Part numbers marked with an asterisk (\*) are contained in Standard Repair Kit No. 300814.

Part numbers marked with a dagger (†) are contained in Viton Seal Kit No. 300815.

Part numbers marked with a bullet (•) are contained in EPR Seal Kit No. 300816.

Sheet No.	2 of 2
Rev 10	Date: 24 Oct 2003

## **DETAIL "A"**



Item No.	Part No.	No. Req'd	Description
1	29365	1	Release Valve Button
2	*10266	1	O-ring (3/8 X 1/4 X 1/16; Nitrile)
	†11438	1	O-ring (3/8 X 1/4 X 1/16; Vition)
	•17715	1	O-ring (3/8 X 1/4 X 1/16; EPR)
3	251297	1	Spring (.36 OD x .51 x .05 ws)
4	34377	1	Poppet Retainer
5	*15279	1	O-ring (1/2 X 3/8 X 1/16; Nitrile)
	†19775	1	O-ring (1/2 X 3/8 X 1/16; Viton)
	•17716	1	O-ring (1/2 X 3/8 X 1/16; EPR)
6	†•*103 <b>7</b> 5	1	Steel Ball (1/4 Dia.)
7	25685	1	Ball Retainer
8	†•*1462 <b>4</b>	1	Compression Spring (1/4 O.D. X 3/4 Lg.)

Part numbers marked with an asterisk (\*) are contained in Standard Repair Kit No. 300814.

Part numbers marked with a dagger (†) are contained in Viton Seal Kit No. 300815.

Part numbers marked with a bullet (•) are contained in Viton Seal Kit No. 300816.

Refer to any operating instructions included with the product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine Power Team replacement parts!** 

Additional questions can be directed to our Technical Services Department.